

SEP 28 1989

DATE: SEPT. 25, 1989

NUMBER: _____

RENTON
CHEMICAL DISPOSAL OR TRANSFER

FACILITIES REQUEST FOR INSTRUCTIONS:

MATERIAL IDENTITY: OILY WATER FROM STORM DRAIN CATCH BASIN - UNDER CLAPPER VALVE ONLY.

MATERIAL LOCATION: PLANT RENTON BLDG. 4-86 DOOR _____ COL. _____ TANK _____

PHYSICAL STATE: ☐ SOLID ☒ LIQUID ☐ SLUDGE ☐ OTHER

ESTIMATED QUANTITY: SAMPLE ONLY - 65-GAL DRUMS OTHER CONTAINERS: TYPE _____ QUANTITY _____

NAME: TOM GRIME PHONE: 237-8799

I NEED:

AS SOON AS POSSIBLE

☐ LAB ANALYSIS & ~~DISPOSAL~~ INSTRUCTIONS (EITHER MANIFEST OR DISCHARGE LETTER)

☐ HAZARDOUS WASTE MANIFEST

☐ TRANSFER AUTHORIZATIONS: FROM _____ TO _____

☐ OTHER _____


PHONE LAB RESULTS TO: NAME TOM GRIME PHONE 237-8799

LAB INSTRUCTIONS:

DISPOSAL OR TRANSFER INSTRUCTIONS: JOYCE / LINDA RENTON Q.C. LAB

ANALYSIS OF SUBMITTED SAMPLE: (PPM) except where noted.

STORM DRAIN



SWAMP WATER -
NO SURFACANT smell
Sept. 25 100 PPM
SAMPLE TO QC LAB
WADS

OF-002

SAMPLE TO QC LAB Sept. 25 100 PPM
WADS

RETG003/REVISED 08-12-88